



# Metallic Ink



Layer Diagram



Alignment

**Carefully Align Elements**  
Metallic Ink Layer areas should be vector format (PDF, Illustrator)

*Avoid areas where you plan to thermal print*



Metallic Ink Result

**Metallic Prints**  
Colors aligned with the Metallic Ink Layer's areas will have a metal shine. Areas not indicated in the Metallic Ink Layer will not be shiny.

*Metallic printing works best with lighter colors.*



**Important**

Place all your Metallic Ink area's vector art on its own layer, and name this layer "Silver." In the Swatches Panel (Illustrator, InDesign), create a New Swatch fill color: Name it "Silver;" in the "Color Type" dropdown select "Spot Color;" apply this swatch to everything on the "Silver" layer.